į	•	Approved For Release 2004/07/08 CIA-RDR81B00878R090600020014-4									
	27 (27 (27 (27) 27 (27) (27 (27) 27 (27) (27) (28)	: 1008Z 24 S	SEPT 59		SEC	RET	2 2 2 2 3 4 5 6 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8			SE CONTRACTO O CON	alle de la constantina del constantina de la con
25X1	DIRECTOR									84	
	A.UK.			<i>f.</i> .			yêrê neg		विकास के कारण है। का अके कारण है कि की कि	ki Apple Nasi Lad	. ilau
	POLICE DPD (1,2,3,4,5,6,7,8,9,1)				DOCUMENT NO. NO CHANGE IN SLASS.			OPERA!	IONAL_IM	EDIATE	# 12 T
:	P\$ 34	s/c (11) HD			CL" .	SE,FIED "NGED TOI IEW DATEI .	TS S O Z	1011	in Ø8		5X1
:	gg s seemanaa	TOR: 1008	24 SEPT !	59	DATE	13/51 REVI	EWERI			<u></u>	5X1 5X1
25X1	Record of common of the common	OPIM		EVE O	OPIM			<u> </u>	≨ <sub>0</sub> )		5X1
25X1		ATTAL O I	IOLINI SONI I	EDAM							

- 1. LAST FLIGHT OF TRAINING SERIES WAS A SIMULATED MISSION PERFORMED THURSDAY, 24. DURING GCA FINAL, 7 MILES FROM THE FIELD THE ENGINE FLAMED OUT. RESTART ATTEMPTS WERE UNSUCCESSFUL. PILOT LANDED GEAR UP ON A SMALL CLIDER FIELD. PILOT UNHURT, AIRCRAFT BADLY DAMAGED.
  - 2. FUEL TOTALIZER 82 GALLONS AT FLAMEOUT. LOW LEVEL LIGHT CAME ON DURING GCA MANEUVERS AT TWELVE THOUSAND FT AND TOTALIZER READING 10/2 GALLONS. ASSUME THAT ALL FUEL TANKS ARE EMPTY BUT THIS HAS NOT BEEN VERIFIED. SUSPECT INTERMITTENT FAULT IN FUEL COUNTER SYSTEM PUZZLED AT SHORTNESS OF TIME BETWEEN LOW LEVEL LIGHT AND FLAMEOUT. TOTAL TIME OF FLIGHT WAS EIGHT AND ONE HALF HOURS.
  - 3. THE WINGS ARE NOT BADLY DAMAGED BUT THE FUESELAGE IS.
    WHETHER IT IS REPAIRABLE ISN'T YET OBVIOUS. DISASSEMBLY WILL BE VERY
    DIFFICULT AND THIS WORK NOW PROCEEDING.
    - 4. IF PHONE CALL DESIRED LET ME KNOW.

END OF MESSAGE